



DATE: January 22, 1997
DESCRIPTION: 2. Roll-offs being loaded onto truck for removal off site SITE: Yurgin Motors east perimeter of site contaminated soil, staged in the south SITE: Yurgin Motors DATE: January 22, 1997 DESCRIPTION: 1. Roll-offs of

SITE: Yurgin Motors
DATE: January 22, 1997
DESCRIPTION: 3. Roll-offs being loaded onto truck for removal off site







SITE: Yurgin Motors

DATE: January 22, 1997 DESCRIPTION: 4. Roll-offs being loaded onto truck for removal off site

SITE: Yurgin Motors

DATE: January 22, 1997
DESCRIPTION: 5. Roll-offs being loaded onto truck for removal off site SITE: Yurgin Motors
DATE: January 22, 1997
DESCRIPTION: 6. Roll-offs being loaded onto truck for removal off site





SITE: Yurgin Motors

DATE: January 22, 1997
DESCRIPTION: 7. Roll-offs being loaded onto truck for removal offsite

SITE: Yurgin Motors

DATE: January 22, 1997 DESCRIPTION: 8. Roll-offs being loaded onto truck for removal off site

DESCRIPTION: 9. Roll-offs being loaded onto truck for removal off site SITE: Yurgin Motors DATE: January 22, 1997



SITE: Yurgin Motors DATE: January 22, 1997

DESCRIPTION: 10. Roll-offs being loaded onto truck for removal off site

SITE: Yurgin Motors

DATE: January 22, 1997
DESCRIPTION: 11. Roll-off's being loaded onto truck for removal off site

DATE: January 22, 1997 DESCRIPTION: 12. Roll-offs being loaded onto truck for removal off site







SITE: Yurgin Motors
DATE: January 22, 1997
DESCRIPTION: 13. Roll-offs being loaded onto truck for removal off site

SITE: Yurgin Motors DATE: January 22, 1997

DESCRIPTION: 14. Roll-offs being loaded onto truck for removal off site

SITE: Yurgin Motors
DATE: January 22, 1997
DESCRIPTION: 15. Roll-offs being loaded onto truck for removal off site







SITE: Yurgin Motors DATE: January 22, 1997 DESCRIPTION: 16. Roll-offs of contaminated soil, staged in the south east perimeter of site

SITE: Yurgin Motors
DATE: January 27, 1997
DESCRIPTION: 17. Excavation of contaminated soil north east perimeter of the site

SITE: Yurgin Motors
DATE: January 27, 1997
DESCRIPTION: 18. Excavated soil being placed into roll-off



SITE: Yurgin Motors
DATE: January 27, 1997
DESCRIPTION: 19. Excavation of contaminated soil north east perimeter of the site

SITE: Yurgin Motors DATE: January 27, 1997 DESCRIPTION: 20. Excavation of contaminated soil north east perimeter of the site SITE: Yurgin Motors
DATE: January 27, 1997
DESCRIPTION: 21. Excavated soil being placed into roll-off







SITE: Yurgin Motors DATE: January 27, 1997 DESCRIPTION: 22. Excavation of contaminated soil north east perimeter of the site

SITE: Yurgin Motors DATE: January 27, 1997 DESCRIPTION: 23. Excavation of

contaminated soil north east

perimeter of the site

DESCRIPTION: 24. Excavation of







SITE: Yurgin Motors

DATE: January 27, 1997 DESCRIPTION: 25. Excavation of

contaminated soil north east

perimeter of the site

SITE: Yurgin Motors DATE: January 29, 1997 DESCRIPTION: 26. Empty trailer

SITE: Yurgin Motors
DATE: January 29, 1997
DESCRIPTION: 27. Trailer, roll-off
excavator, drum staging area







SITE: Yurgin Motors DATE: January 29, 1997 DESCRIPTION: 28. Excavator, bobcat, drum staging area

SITE: Yurgin Motors DATE: January 29, 1997 DESCRIPTION: 29. Excavator, roll-

off, bobcat, drum staging area

SITE: Yurgin Motors
DATE: January 29, 1997
DESCRIPTION: 30. Drums being loaded onto trailer





SITE: Yurgin Motors DATE: January 29, 1997

DESCRIPTION: 31. Drums being

loaded onto trailer

SITE: Yurgin Motors DATE: January 29, 1997 DESCRIPTION: 32. Drums being

loaded onto bobcat

SITE: Yurgin Motors
DATE: January 29, 1997
DESCRIPTION: 33. Drums being loaded onto bobcat







SITE: Yurgin Motors DATE: January 29, 1997 DESCRIPTION: 34. Drums being

loaded onto trailer via bobcat

SITE: Yurgin Motors DATE: January 29, 1997 DESCRIPTION: 36. Drums staging

area at completion

SITE: Yurgin Motors
DATE: January 29, 1997
DESCRIPTION: 35. Drum staging
area at 75% completion of removal